



The “Chemical Risk Map” Four dominant risk domains:



1 **Moisture** —
System Coupling Variable



2 **Oxidation** —
Degradation Engine



3 **Corrosive Sulphur**

4 **Thermal & Electrical Faults**

**Transformer Degradation Is Not One Problem
— It's a Chemical Risk Map**